**PATENT** 



#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	) Evenines W Dens	Examiner: W. Benson
YASUDA, ET AL.	·	
Appl. No.: 10/551,112	Group Art Unit: 2858	" , ,
Filed: March 26, 2004	)	
For: MICROMECHANICAL POTENTIAL SENSOR		
U.S. Patent No.: 7,274,193 B2		
Issued: September 25, 2007	March 20, 2008	<b>Certificate</b>
Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450		MAR 2 5 2008 of Correction

# REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

03/24/2008 DEMMANU1 00000003 7274193

01 FC:1811

100.00 OP COEVED-USPTO Calcal Publication

MAR 2 5 2008

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Edward A. Kmett Attorney for Patentees Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS\_WS 2005598v1

- 2 -

## UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO. : 7,274,193 B2

DATED : September 25, 2007

INVENTOR(S) : Yasuda, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 5:

Line 29, "same" should read -- the same --.

#### COLUMN 6:

Line 3, "same" should read -- the same --.

#### COLUMN 9:

Line 30, "member" should read -- member is --; and Line 39, "with in" should read -- within --.

### COLUMN 10:

Line 1, "configure" should read -- configured --; and Line 38, "include" should read -- includes --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>7,274,193 B2</u>

No. of add Propies PTO @ 30¢ per page こばっか

MAR 2 5 2008

Form PTO 1050 (Rev. 3-82) 2007784v1(Form#30)

## UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

**PATENT NO.** : 7,27

: 7,274,193 B2

DATED

: September 25, 2007

INVENTOR(S) : Yasuda, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 5:

Line 29, "same" should read -- the same --.

#### COLUMN 6:

Line 3, "same" should read -- the same --.

#### COLUMN 9:

Line 30, "member" should read -- member is --; and Line 39, "with in" should read -- within --.

### COLUMN 10:

Line 1, "configure" should read -- configured --; and Line 38, "include" should read -- includes --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 7;274,193 B2

No. of add'l. copies @ 30¢ per page 2008

